

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Client:		Site: FILL THE FLOOR DISCOS		
Asset ID: 001	Description: SPEAKER	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 002	Description: MOVING HEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 003	Description: MOVING HEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 004	Description: WIZARD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 005	Description: WIZARD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 006	Description: MOVING HEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 007	Description: MOVING HEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 008	Description: POWER LEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 009	Description: TV	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 010	Description: TV	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Asset ID: 011	Description: TV	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 012	Description: TV	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 013	Description: RUBIX LIGHT	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 014	Description: RUBIX LIGHT	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 015	Description: DOTZ MATRIX	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 016	Description: DOTZ MATRIX	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 017	Description: MICS	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 018	Description: CITRONIC LIGHT	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 019	Description: CITRONIC	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 020	Description: MOVING HEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Asset ID: 021	Description: MOVING HEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 022	Description: SPEAKER		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 023	Description: SPEAKER		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 024	Description: SUB SPEAKER		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 025	Description: CONTROLLER		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 026	Description: WIRELESS TRANS		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 027	Description: POWER POINT		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 028	Description: PRINTER		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 029	Description: KETTLE LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 030	Description: POWER UNIT		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Asset ID: 031		Description: POWER LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 032		Description: STARCLOTH		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 033		Description: POWER LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 034		Description: POWER LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 035		Description: NUMBER 5		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 036		Description: NUMBER 0		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 037		Description: NUMBER 1		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 038		Description: NUMBER 2		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 039		Description: NUMBER 3		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					
Asset ID: 040		Description: NUMBER 4		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	
Overall: Pass					

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Asset ID: 041	Description: KETTLE LEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Earth Current	18/08/2026	25	A	Information
Earth	18/08/2026	0.08	Ohm	Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Polarity	18/08/2026			Pass
Overall: Pass				
Asset ID: 042	Description: W	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 043	Description: &	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 044	Description: 4	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 045	Description: A	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 046	Description: B	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 047	Description: B	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 048	Description: C	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 049	Description: L	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass
Overall: Pass				
Asset ID: 050	Description: O	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Overall: Pass

Asset ID: 051		Description: O		User: DEMO NOVCE		Test Instrument: X20-0173	
Test Type		Date	Result		Unit	Status	
Visual		18/08/2026				Pass	
Insulation		18/08/2026	>99.99		MOhm	Pass	
Touch Leakage		18/08/2026	<0.1		mA	Pass	

Overall: Pass

Asset ID: 052		Description: 9		User: DEMO NOVCE		Test Instrument: X20-0173	
Test Type		Date	Result		Unit	Status	
Visual		18/08/2026				Pass	
Insulation		18/08/2026	>99.99		MOhm	Pass	
Touch Leakage		18/08/2026	<0.1		mA	Pass	

Overall: Pass

Asset ID: 053	Description: 6	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 054		Description: T		User: DEMO NOVCE		Test Instrument: X20-0173	
Test Type		Date	Result		Unit	Status	
Visual		18/08/2026				Pass	
Insulation		18/08/2026	>99.99		MOhm	Pass	
Touch Leakage		18/08/2026	<0.1		mA	Pass	

Overall: Pass

Asset ID: 055		Description: M		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	

Overall: Pass

Asset ID: 056		Description: N		User: DEMO NOVCE		Test Instrument: X20-0173	
Test Type		Date	Result		Unit	Status	
Visual		18/08/2026				Pass	
Insulation		18/08/2026	>99.99		MOhm	Pass	
Touch Leakage		18/08/2026	<0.1		mA	Pass	

Overall: Pass

Asset ID: 057		Description: 7		User: DEMO NOVCE		Test Instrument: X20-0173	
Test Type		Date	Result	Unit	Status		
Visual		18/08/2026			Pass		
Insulation		18/08/2026	>99.99	MOhm	Pass		
Touch Leakage		18/08/2026	<0.1	mA	Pass		

Overall: Pass

Asset ID: 058	Description: M	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 059	Description: R	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 060	Description: S	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Overall: Pass

Asset ID: 061	Description: X	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 062	Description: N	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 063	Description: D	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 064	Description: K	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 065	Description: J	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 066	Description: I	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 067	Description: G	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 068	Description: P	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 069	Description: V	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 070	Description: R	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Overall: Pass

Asset ID: 071	Description: KETTLE LEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Earth Current	18/08/2026	25	A	Information
Earth	18/08/2026	0.04	Ohm	Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Polarity	18/08/2026			Pass

Overall: Pass

Asset ID: 072		Description: EXT LEAD		User: DEMO NOVCE		Test Instrument: X20-0173	
Test Type		Date	Result		Unit	Status	
Visual		18/08/2026				Pass	
Earth Current		18/08/2026	25		A	Information	
Earth		18/08/2026	0.07		Ohm	Pass	
Insulation		18/08/2026	>99.99		MOhm	Pass	
Polarity		18/08/2026				Pass	

Overall: Pass

Asset ID: 073	Description: KETTLE LEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Earth Current	18/08/2026	25	A	Information
Earth	18/08/2026	0.08	Ohm	Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Polarity	18/08/2026			Pass

Overall: Pass

Asset ID: 074	Description: EXT LEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Earth Current	18/08/2026	25	A	Information
Earth	18/08/2026	0.11	Ohm	Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Polarity	18/08/2026			Pass

Overall: Pass

Asset ID: 075	Description: KETTLE LEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Earth Current	18/08/2026	25	A	Information
Earth	18/08/2026	0.06	Ohm	Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Polarity	18/08/2026			Pass

Overall: Pass

Asset ID: 076		Description: POWER LEAD		User: DEMO NOVCE		Test Instrument: X20-0173	
Test Type		Date	Result		Unit	Status	
Visual		18/08/2026				Pass	
Insulation		18/08/2026	>99.99		MOhm	Pass	
Touch Leakage		18/08/2026	<0.1		mA	Pass	

Overall: Pass

Asset ID: 077	Description: KETTLE LEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Earth Current	18/08/2026	25	A	Information
Earth	18/08/2026	0.04	Ohm	Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Polarity	18/08/2026			Pass

Overall: Pass

Asset ID: 078	Description: KETTLE LEAD	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Earth Current	18/08/2026	25	A	Information
Earth	18/08/2026	0.1	Ohm	Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Polarity	18/08/2026			Pass

Overall: Pass

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Asset ID: 079	Description: KETTLE LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Earth Current	18/08/2026	25	A	Information
Earth	18/08/2026	0.04	Ohm	Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Polarity	18/08/2026			Pass

Overall: Pass

Asset ID: 080		Description: EXT LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Earth Current	18/08/2026	25	A	Information	
Earth	18/08/2026	0.11	Ohm	Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Polarity	18/08/2026			Pass	

Overall: Pass

Asset ID: 081		Description: POWER LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	

Overall: Pass

Asset ID: 082		Description: KETTLE LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Earth Current	18/08/2026	100	mA a.c.	Information	
Earth	18/08/2026	0.19	Ohm	Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Polarity	18/08/2026			Pass	

Overall: Pass

Asset ID: 083		Description: EXT LEAD		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Earth Current	18/08/2026	100	mA a.c.	Information	
Earth	18/08/2026	0.22	Ohm	Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Polarity	18/08/2026			Pass	

Overall: Pass

Asset ID: 084	Description: PHOTO MIRROR	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Asset ID: 085		Description: SELFIE BOOTH		User: DEMO NOVCE		Test Instrument: X20-0173	
Test Type		Date	Result		Unit	Status	
Visual		18/08/2026				Pass	
Insulation		18/08/2026	>99.99		MOhm	Pass	
Touch Leakage		18/08/2026	<0.1		mA	Pass	

Overall: Pass

Asset ID: 086		Description: SELFIE BOOTH		User: DEMO NOVCE	Test Instrument: X20-0173
Test Type	Date	Result	Unit	Status	
Visual	18/08/2026			Pass	
Insulation	18/08/2026	>99.99	MOhm	Pass	
Touch Leakage	18/08/2026	<0.1	mA	Pass	

Overall: Pass

Asset ID: 087	Description: LAPTOP	User: DEMO NOVCE	Test Instrument: X20-0173	
Test Type	Date	Result	Unit	Status
Visual	18/08/2026			Pass
Insulation	18/08/2026	>99.99	MOhm	Pass
Touch Leakage	18/08/2026	<0.1	mA	Pass

Overall: Pass

Detailed Test History

Test Status: All, Test Type: All
Person: All, Instrument: All
From: 18/08/2026 To: 18/08/2027

Total Tests: 87